GK-KIT-050 Instructions

1. Attach 4 of the black M2x10mm screws and nuts to the corners of the base.
2. Remove the adhesive strip cover from the bottom of the battery holder.
3. Attach the battery holder centered with the long side aligned to the front edge of the base on the same side as the M2x10 screw heads.
4. Attach one bracket to each of the two vertical supports using two M2x10 screws and nuts with the screw heads on the bracket.
5. Attach the arm at the second hole from the end to the second hole down on the vertical supports with the M2x30mm chrome screw and nut.
6. Attach the complete arm and vertical support centered against the battery holder with 4 of the M2x12 black crews and nuts.
7. Twist the red and black wires from the battery holder and pass them through the seventh hole from the back of the arm.
8. Pass the red wire back through the arm in the opposite direction through the ninth hole from the back of the arm.
9. Insert the two LED wire connectors in opposite directions through first and second holes at the front of the arm.
10. Insert the LED into the two wire connectors in either direction.
11. Twist together the red wire from the battery pack to one of the wires from the LED.
12. Twist together the black wire from the battery pack to the other wire from the LED.
13. Insert two AA batteries into the holder.
14. Turn the switch on (to the front).
15. If the LED does not light reverse the LED in the connectors.
16. If the LED still does not light, make sure both twisted wires are making good contact.